



Figure 3.13. Orthophoto with GIS and photointerpretation coverage showing disturbance history in an area where human-caused sediment delivery is interpreted to be in the 75 percent category. North Fork Kelsey Creek.