

Station Name	Station Code	Sample Date	Collection Time	Group	Discharge, cfs	DO, 7 mg/L	pH	SC, 700 μ S/cm	Comments
Berenda Slough along Ave 18 1/2	545XSAAE	9/11/2012	9:10	Irrigation5, Management Plan Monitoring	NA				Dry site, no water samples collected. September Management Plan Monitoring for copper and chlorpyrifos.
Deadman Creek @ Hwy 59	535DMCAHF	9/11/2012	10:00	Irrigation5, Management Plan Monitoring	4.19	4.92			September Management Plan Monitoring for chlorpyrifos. Pesticides analyzed in toxic sediment only.
Highline Canal @ Lombardy Rd	535XHCALR	9/11/2012	13:20	Irrigation5	NA				Pesticides analyzed in toxic sediment only. Too deep to measure discharge.
Levee Drain @ Carpenter Rd	535XLDACR	9/11/2012	13:00	Irrigation5	0.92	4.6		1864	Pesticides analyzed in toxic sediment only.
McCoy Lateral @ Hwy 140	535XMLAHO	9/11/2012	11:40	Irrigation5, Management Plan Monitoring	5.31		8.74		September Management Plan Monitoring for copper. Pesticides analyzed in toxic sediment only.
Rodden Creek @ Rodden Rd	535XRCARD	9/11/2012	9:30	Irrigation5	2.85				Pesticides analyzed in toxic sediment only.

NA - Not applicable; see comments.