

**STATE OF CALIFORNIA
CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD
LOS ANGELES REGION
320 West 4th Street, Suite 200, Los Angeles, California 90013**

**FACT SHEET
WASTE DISCHARGE REQUIREMENTS
FOR
DEPARTMENT OF PUBLIC WORKS
(PUBLIC WORKS ROAD MAINTENANCE YARD NO. 336)
3637 WINTER CANYON ROAD**

**ORDER NO. 01- 031
FILE NO. 02- 113**

FACILITY ADDRESS

3637 Winter Canyon Road
Malibu, CA 90265

FACILITY MAILING ADDRESS

900 South Fremont Avenue, 2nd Fl.
Alhambra, CA 91803

PROJECT DESCRIPTION:

Public Works Road Maintenance Yard No. 336 is located at 3637 Winter Canyon Road in the City of Malibu. Yard No. 336 consists of three facilities: an office building, a garage/crew room, and a maintenance yard. The office building contains one restroom, which has a toilet, a urinal, and a sink. The garage/crew room has two showers, two urinals, three toilets and three sinks.

The septic system at the facility consists of two sanitary sewer tank manholes approximately 50 feet south of the office building. These tanks allow sewage to flow south (down-gradient) approximately 80 feet to the leach field. The leach field is approximately 20 feet X 50 feet.

The discharge volume for the facility is estimated to be 117 gallons per day (gpd). The groundwater elevation is estimated to be approximately 72 feet from the ground surface (53 feet above mean sea level). The regional groundwater flow is southeasterly and is ultimately toward the ocean. The groundwater flow in the vicinity of the subject facility flows southwesterly or toward Winter Canyon Wash.

VOLUME AND DESCRIPTION OF DISCHARGE:

Public Works Road Maintenance Yard No. 336 (Latitude: 34°02'24", Longitude: 118°32'00") is estimated to discharge 117 gallons per day (gpd) into the septic tank system. The wastewater is composed of typical residential wastewater.