



California Regional Water Quality Control Board San Diego Region



Linda S. Adams
Acting Secretary for
Environmental Protection

Over 50 Years Serving San Diego, Orange, and Riverside Counties
Recipient of the 2004 Environmental Award for Outstanding Achievement from USEPA

Edmund G. Brown, Jr.
Governor

9174 Sky Park Court, Suite 100, San Diego, California 92123-4353
(858) 467-2952 • Fax (858) 571-6972
[http:// www.waterboards.ca.gov/sandiego](http://www.waterboards.ca.gov/sandiego)

January 20, 2011

In reply refer to:
224137:adai

Mr. Jack Bebee
Engineering and Planning Manager
Fallbrook Public Utility District
990 East Mission Road
P.O. Box 2290
Fallbrook, CA 92088-2290

Dear Mr. Bebee:

SUBJECT: FALLBROOK PUBLIC UTILITY DISTRICT TREATMENT PLANT NO. 1

The California Regional Water Quality Control Board, San Diego Region (San Diego Water Board) has reviewed the September, October, and November 2010 monthly and the July-September 2010 quarterly monitoring reports submitted by the Fallbrook Public Utility District (District) in accordance with Monitoring and Reporting Program No. 91-39.

The San Diego Water Board identified the following violation of the Order No. 91-39:

The 30-day average discharge specification for fluoride, established at 1.0 milligrams per liter (mg/L), was exceeded for September 2010 with a reported value of 1.2 mg/L. It is our understanding that results of subsequent effluent samples analyzed for fluoride were below 1.2 mg/L. The San Diego Water Board is also in the process of reviewing the District's request for relaxing effluent discharge specification for fluoride.

The next monitoring report to be submitted is the November 2010 monthly monitoring report which is due by December 30, 2010.

For questions pertaining to the subject matter, please contact Amanda Dai at (858) 627-3977 or via email at adai@waterboards.ca.gov.

**PLEASE INCLUDE "224137:ADAI" IN THE SUBJECT LINE OF FUTURE
CORRESPONDANCE.**

Sincerely,

A handwritten signature in black ink, appearing to read 'B. Tobler', with a long horizontal stroke extending to the right.

Ben Tobler
Water Resource Control Engineer
Cleanup and Land Discharge Branch

Regulatory Measure: 376392
CIWQS Violation: 883755