



San Diego Regional Water Quality Control Board

June 8, 2017

Mr. Ken Johansson California Department of Transportation 4050 Taylor Street, MS 242 San Diego, CA 92110 In reply refer to / attn: 642697:BBushnell

Subject: Review of Monitoring Reports for Order No. R9-2007-0148, Tecate Truck Inspection Station

Mr. Johansson:

The California Regional Water Quality Control Board, San Diego Region (San Diego Water Board) has reviewed the 2016 annual monitoring report. California Department of Transportation (the Discharger) submitted the monitoring reports as required by the Monitoring and Reporting Program No. R9-2007-0148.

The San Diego Water Board found the following violation in the report provided:

1. Monitoring and Reporting Program No. R9-2007-0148, Section F, Report Schedule, specifies the annual monitoring report is due February 1 of the following year. The San Diego Water Board has no record that the annual 2015 monitoring report was received from the Discharger.

The next monitoring report due is the July-December 2017 semiannual report, which is due by February 1, 2018.

Please continue to implement follow-up actions necessary to ensure that the violations noted above do not occur in the future. These violations may subject the Discharger to possible further enforcement action by the San Diego Water Board including but not limited to: administrative enforcement orders requiring the Discharger to cease and desist from violations, or administrative assessments of civil liabilities in amounts of up to \$5,000 per day per violation; referral to the State Attorney General for injunctive relief; and referral to the District Attorney for criminal prosecution.

In the subject line of any response, please include reference **642697**:**BBushnell**. Please contact Mr. Brandon Bushnell at 619-521-8044, or at bushnell@waterboards.ca.gov if you have any questions or comments.


Sincerely,

John R. Odermatt, M.Sc., P.G., Senior Engineering Geologist

Land Discharge Unit

- h.o lett

JRO: ac: bb



	Tech Staff Info & Use
Place ID	642697
Reg. Measure ID	314258
SEL Reg. Measure ID	413554
Violation ID	1025442