

C-117

C-119



C-121

C-123



C-125




C-122



C-124





C-129



C-128



C-127

C-124

C-130



C-131



C-132



C-133



C-135



C-134



C-137



C-136




C-139




C-141



C-138



C-140



C-143



C-145




C-142




C-144



C-147



C-146



C-149




C-148



C-151




C-153




C-150



C-152




C-155



C-157



C-154




C-156



C-159



C-158



C-161



C-160




C-1163



C-1165



C-1162



C-1164



C-1167




C-1169



C-1164



C-1168



C-170



C-171



C-172




C-173



C-175



C-177




C-174




C-176





C-181



C-180



C-183



C-185



C-182



C-184




C-184




C-187




C-188




C-189



C-191



C-193



C-190




C-192



C-195



C-194




C-197




C-194



C-199




C-200



C-198



C-201



C-203



C-205



C-202




C-201



C-207




C-209



C-206



C-208



C-211



C-210




C-213




C-212




C-215




C-217




C-214



C-216



C-219



C-218



C-221




0E2-0



C-223



0E2-0



C-225



C-225




C-227



C-226




C-229




C-229




C-231




C-230



C-233




C-232



C-235



C-234




C-237



C-234




C-238 ?



C-240




C-239



C-242



C-241



C-244



C-243



C-245



C-246




C-248




C-250



C-247



C-249



C-252



C-254



C-251



C-253




C-254



C-255




C-257




C-259




C-261



C-258




C-260



C-263




C-265




C-262




C-264




C-267




C-269



C-268




C-268




C-270




C-271



C-272



C-273



C-274




C-274


C-275



C-277



C-279



C-278



C-287



C-283



C-280



C-282




C-285



C-287



C-284



C-284



68E-D



18E-D



88E-D



09E-D




C-293



C-295



C-292



C-294





C-298

C-299



C-301



C-303




C-300



C-302



Q-305




Q-304



C-307



C-309



C-304




C-308



C-311



C-310



C-313



C-312



C-314



C-315




C-316



C-317




C-318



C-319



C-320



C-321



C-322



C-303



C-304



C-305



C-304



C-328



3-330



C-327




C-329



C-332



C-331



C-334



C-333



C-336



C-338



C-335



C-337



C-340



C-339



C-342



C-341



C-343



C-344



C-345



C-346



C-348



C-350



California's beautiful natural landscapes have been invaded by plants from other parts of the world. Some came by accident (sideways in cargo on trucks, in animal droppings, or in soil) but most came by human activities for agriculture or ornamental landscaping. Virtually all of these invaders are difficult and costly to remove. The presence of non-native plants also called invasives or exotics changes the ecosystem by:

- pushing spreading and displacing local plants and animals
- changing the feeding patterns of local wildlife
- creating fire hazards
- reducing water availability

You can help by using natives or plants that will not escape your yard or that won't affect the local native ecosystem. You can also volunteer to help remove invasive plants and restore habitats.

C-347



C-349



California's beautiful natural landscapes have been invaded by plants from other parts of the world. Some came by accident (sideways in cargo on trucks, in animal droppings, or in soil) but most came by human activities for agriculture or ornamental landscaping. Virtually all of these invaders are difficult and costly to remove. The presence of non-native plants also called invasives or exotics changes the ecosystem by:

- pushing spreading and displacing local plants and animals
- changing the feeding patterns of local wildlife
- creating fire hazards
- reducing water availability

You can help by using natives or plants that will not escape your yard or that won't affect the local native ecosystem. You can also volunteer to help remove invasive plants and restore habitats.

C-352



C-354



C-351



C-353



C-3574



C-355



C-357



C-359



C-361



C-358



C-360



C-363




C-365



C-362



C-364



3-367



C-369



C-364



C-368



C-371




C-370



C-373



C-372



C-375



C-377



C-374



C-376




C-379




C-381



C-378



C-380



C-382



C-383



C-384



C-385



C-384



C-388



C-390



C-387



C-389



C-392



C-394



C-391



C-393



C-395



C-396



C-397



C-398



C-400



C-402




C-399



C-401



C-404



C-406



C-403




C-405




C-407




C-408



C-409



C-410



C-411




C-412



C-414



C-413




C-414



C-418



C-415



C-417



C-400




C-402



C-419



C-421



C-424




C-424

C-423



C-425



C-428



C-427



C-430



C-429



C-431



C-433



C-434



**Buena Vista Spill Photos
City of Vista**

PHOTO #	DATE	TIME	PHOTOGRAPHER	PHOTO SUMMARY	PHOTO RELEVANCE
E-1	4/2/07	9:00 AM	George Solano, Waste Water Supervisor	Flow rate of spill site	Document spill event
E-2	4/2/07		George Solano, Waste Water Supervisor	Spill site	Documentation of spill site
E-3	4/2/07	10-11:00 AM	George Solano, Waste Water Supervisor	Pump station slowing down flow into 24" line to reduce flow into lagoon by flooding into station	Document spill event
E-4	4/2/07	10-11:00 AM	George Solano, Waste Water Supervisor	Pump station slowing down flow into 24" line to reduce flow into lagoon by flooding into station	Document spill event
E-5	4/2/07	10-11:00 AM	George Solano, Waste Water Supervisor	Pump station slowing down flow into 24" line to reduce flow into lagoon by flooding into station	Document spill event
E-6	4/2/07	11:00 AM	George Solano, Waste Water Supervisor	Mutual aid response. Vactor trucks from Vista, Carlsbad, Leucadia, preparing to assist with pump-out at pump station	Document spill event
E-7	4/2/07	11:00 AM	George Solano, Waste Water Supervisor	Mutual aid response. Vactor trucks from Vista, Carlsbad, Leucadia, preparing to assist with pump-out at pump station	Document spill event
E-8	4/2/07	11:00 AM	George Solano, Waste Water Supervisor	Mutual aid response. Vactor trucks from Vista, Carlsbad, Leucadia, preparing to assist with pump-out at pump station	Document spill event
E-9	4/2/07	11:00 AM	George Solano, Waste Water Supervisor	Mutual aid response. Vactor trucks from Vista, Carlsbad, Leucadia, preparing to assist with pump-out at pump station	Document spill event
E-10	4/2/07	11:00 AM	George Solano, Waste Water Supervisor	Photo showing pump operations at pump station. Mitigation of sewage from going into lagoon	Document spill event
E-11	4/2/07	PM	George Solano, Waste Water Supervisor	Carlsbad officials with press	Informing the media and public
E-12	4/2/07	PM	George Solano, Waste Water Supervisor	Carlsbad officials with press	Informing the media and public
E-13	4/2/07	PM	George Solano, Waste Water Supervisor	Carlsbad officials with press	Informing the media and public
E-14	4/2/07	PM	George Solano, Waste Water Supervisor	Carlsbad officials with press	Informing the media and public
E-15	4/2/07	Mid-day	George Solano, Waste Water Supervisor	Mutual aid response by Vista, Carlsbad, Leucadia	Shows City's 24/7 response to incident
E-16	4/2/07	Mid-day	George Solano, Waste Water Supervisor	Mutual aid response by Vista, Carlsbad, Leucadia	Shows City's 24/7 response to incident
E-17	4/2/07	Mid-day	George Solano, Waste Water Supervisor	Mutual aid response by Vista, Carlsbad, Leucadia	Shows City's 24/7 response to incident
E-18	4/2/07	Mid-day	George Solano, Waste Water Supervisor	Mutual aid response by Vista, Carlsbad, Leucadia	Shows City's 24/7 response to incident
E-19	4/2/07	PM	George Solano, Waste Water Supervisor	Photo of spill site	Documentation of spill rate
E-20	4/2/07	12:00 PM	George Solano, Waste Water Supervisor	Photo of contractors shoring panels	Documenting arrival of safety shoring for excavation work
E-21	4/2/07	12:00 PM	George Solano, Waste Water Supervisor	Photo of contractors shoring panels	Documenting arrival of safety shoring for excavation work

**Buena Vista Spill Photos
City of Vista**

PHOTO #	DATE	TIME	PHOTOGRAPHER	PHOTO SUMMARY	PHOTO RELEVANCE
E-22	4/2/07	12:00 PM	George Solano, Waste Water Supervisor	Photo of contractors shoring panels	Documenting arrival of safety shoring for excavation work
E-23	4/2/07	12:00 PM	George Solano, Waste Water Supervisor	Photo of contractors shoring panels	Documenting arrival of safety shoring for excavation work
E-24	4/2/07	12:00 PM	George Solano, Waste Water Supervisor	Photo of contractors shoring panels	Documenting arrival of safety shoring for excavation work
E-25	4/2/07	12:00 PM	George Solano, Waste Water Supervisor	Photo of contractors shoring panels	Documenting arrival of safety shoring for excavation work
E-26	4/2/07	12:00 PM	George Solano, Waste Water Supervisor	Photo of contractors shoring panels	Documenting arrival of safety shoring for excavation work
E-27	4/2/07	12:00 PM	George Solano, Waste Water Supervisor	Photo of contractors shoring panels	Documenting arrival of safety shoring for excavation work
E-28	4/2/07	1:00 PM	George Solano, Waste Water Supervisor	Shoring sheet piles; preparing to be installed	Documentation of efforts to shore excavation to safely dig to pipe
E-29	4/2/07	1:00 PM	George Solano, Waste Water Supervisor	Shoring sheet piles; preparing to be installed	Documentation of efforts to shore excavation to safely dig to pipe
E-30	4/2/07	1:00 PM	George Solano, Waste Water Supervisor	Sheet pile shoring being installed	Documentation of shoring being installed before excavation to pipe can begin
E-31	4/2/07	1:00 PM	George Solano, Waste Water Supervisor	Sheet pile shoring being installed	Documentation of shoring being installed before excavation to pipe can begin
E-32	4/2/07	1:00 PM	George Solano, Waste Water Supervisor	Sheet pile shoring being installed	Documentation of shoring being installed before excavation to pipe can begin
E-33	4/2/07	1:00 PM	George Solano, Waste Water Supervisor	Sheet pile shoring being installed	Documentation of shoring being installed before excavation to pipe can begin
E-34	4/2/07	1:00 PM	George Solano, Waste Water Supervisor	Sheet pile shoring being installed	Documentation of shoring being installed before excavation to pipe can begin
E-35	4/2/07	1:00 PM	George Solano, Waste Water Supervisor	Sheet pile shoring being installed	Documentation of shoring being installed before excavation to pipe can begin
E-36	4/2/07	1:00 PM	George Solano, Waste Water Supervisor	Sheet pile shoring being installed	Documentation of shoring being installed before excavation to pipe can begin
E-37	4/2/07	1:00 PM	George Solano, Waste Water Supervisor	Sheet pile shoring being installed	Documentation of shoring being installed before excavation to pipe can begin
E-38	4/2/07	1:00 PM	George Solano, Waste Water Supervisor	Sheet pile shoring being installed	Documentation of shoring being installed before excavation to pipe can begin
E-39	4/2/07	1:00 PM	George Solano, Waste Water Supervisor	Sheet pile shoring being installed	Documentation of shoring being installed before excavation to pipe can begin
E-40	4/2/07	2:00 PM	George Solano, Waste Water Supervisor	Photo showing size of sheet piles	Documenting size of sheets and process of installation
E-41	4/2/07	3:00 PM	George Solano, Waste Water Supervisor	Photo showing Carlsbad crews exposing 24" main up stream of break	Documenting dig effort

**Buena Vista Spill Photos
City of Vista**

PHOTO #	DATE	TIME	PHOTOGRAPHER	PHOTO SUMMARY	PHOTO RELEVANCE
E-42	4/2/07	3:00 PM	George Solano, Waste Water Supervisor	Photo showing Carlsbad crews exposing 24" main up stream of break	Documenting dig effort
E-43	4/2/07	7:00 PM	George Solano, Waste Water Supervisor	Piles in place	Document time required to install piles
E-44	4/2/07	7:00 PM	George Solano, Waste Water Supervisor	Piles in place	Document time required to install piles
E-45	4/2/07	7-Midnight	George Solano, Waste Water Supervisor	Excavator moving into begin excavation	Documents time between shore; Installed and excavation begins
E-46	4/2/07	7-Midnight	George Solano, Waste Water Supervisor	Excavator removing sewage from spillsite. White compression coupling in photo	Documentation showing 2" water line above 24" sewer line.
E-47	4/2/07	9-Midnight	George Solano, Waste Water Supervisor	City of Vista, 6" trail pump being moved into position	Document City's 24/7 response effort
E-48	4/2/07	PM	George Solano, Waste Water Supervisor	Excavator exposed in a 2" water line approx. 4' above 24" forcemain. Compression repair coupling was also noted in previous photo	Documentation showing 2" water line above 24" sewer line.
E-49	4/3/07	1:00 AM	George Solano, Waste Water Supervisor	City of Vista Crews	Documenting City's 24/7 response efforts
E-50	4/3/07	1:00 AM	George Solano, Waste Water Supervisor	Excavator digging to locate pipe (24" FM). 2" water line next to bucket	Documenting City's 24/7 response efforts
E-51	4/3/07	2:00 AM	George Solano, Waste Water Supervisor	Contractor hand digging to locate 24" F.M.	Documentation of time crews entered excavation site
E-52	4/3/07	2:00 AM	George Solano, Waste Water Supervisor	Contractor hand digging to locate 24" F.M.	Documentation of time crews entered excavation site
E-53	4/3/07	2:00 AM	George Solano, Waste Water Supervisor	Contractor hand digging to locate 24" F.M.	Documentation of time crews entered excavation site
E-54	4/3/07	1:00-3:00 AM	George Solano, Waste Water Supervisor	Crews exposed pipe	Document crews locating and exposing 24" forcemain
E-55	4/3/07	1:00-3:00 AM	George Solano, Waste Water Supervisor	Crews exposed pipe	Document crews locating and exposing 24" forcemain
E-56	4/3/07	1:00-3:00 AM	George Solano, Waste Water Supervisor	Crews exposed pipe	Document crews locating and exposing 24" forcemain
E-57	4/3/07	1:00-3:00 AM	George Solano, Waste Water Supervisor	Crews exposed pipe	Document crews locating and exposing 24" forcemain
E-58	4/3/07	1:00-3:00 AM	George Solano, Waste Water Supervisor	Crews exposed pipe	Document crews locating and exposing 24" forcemain
E-59	4/3/07	4:00-6:00 AM	George Solano, Waste Water Supervisor	Contractor crews begin cutting pipe	Document crews begin cutting pipe to remove damaged section
E-60	4/3/07	4:00-6:00 AM	George Solano, Waste Water Supervisor	Contractor crews begin cutting pipe	Document crews begin cutting pipe to remove damaged section
E-61	4/3/07	4:00-6:00 AM	George Solano, Waste Water Supervisor	Contractor crews begin cutting pipe	Document crews begin cutting pipe to remove damaged section
E-62	4/3/07	4:00-6:00 AM	George Solano, Waste Water Supervisor	Contractor crews begin cutting pipe	Document crews begin cutting pipe to remove damaged section

E-1



E-2



E-3



E-4



E-6




E-8



E-5



E-7



E-9



E-10



E-12



E-11



E-14



E-13



E-16



E-18



E-15



E-17



E-19



E-20



E-21



E-22



E-23



E-24



E-25



E-26



E-27



E-28



E-29



E-30



E-31



E-32



E-33



E-34



E-34



E-38



E-35




E-37



E-39



E-40




E-41



E-42




E-43



E-44



E-45



E-46



E-47



E-48



F-49




~~49~~ E-50




E-51



E-52



E-53



E-54



E-55



E-56




E-57



E-58



E-60



E-62



E-59



E-61



Buena Vista Spill Photos City of Vista

PHOTO #	DATE	TIME	PHOTOGRAPHER	PHOTO SUMMARY	PHOTO RELEVANCE
V-1	4/3/07	10:30 AM	Rick Dudley, Asst City Manager	Repair effort in progress	Quick action to contain spill
V-2	4/3/07	10:30 AM	Rick Dudley, Asst City Manager	Repair effort in progress	Quick action to contain spill
V-3	4/3/07		Rick Dudley, Asst City Manager	Vista City Attorney Darold Pieper views the failed portion of pipe	Quick action to contain spill
V-4	4/3/07		Rick Dudley, Asst City Manager	Vista City Attorney Darold Pieper views the failed portion of pipe	Quick action to contain spill
V-5	4/3/07	10:35 AM	Rick Dudley, Asst City Manager	Failed portion of pipe	Document failed pipe
V-6	4/3/07	10:35 AM	Rick Dudley, Asst City Manager	Failed portion of pipe	Document failed pipe
V-7	4/3/07	10:35 AM	Rick Dudley, Asst City Manager	Failed portion of pipe	Document failed pipe
V-8	4/3/07	10:35 AM	Rick Dudley, Asst City Manager	Close-up of failed portion of pipe	Document failed pipe
V-9	4/3/07	10:35 AM	Rick Dudley, Asst City Manager	Close-up of failed portion of pipe	Document failed pipe
V-10	4/3/07	10:35 AM	Rick Dudley, Asst City Manager	Close-up of failed portion of pipe	Document failed pipe
V-11	4/3/07	10:35 AM	Rick Dudley, Asst City Manager	Close-up of failed portion of pipe	Document failed pipe
V-12	4/3/07	10:40 AM	Rick Dudley, Asst City Manager	Repair work taking place on pipe	Quick action to contain spill
V-13	4/3/07	10:40 AM	Rick Dudley, Asst City Manager	Repair work taking place on pipe	Quick action to contain spill
V-14	4/3/07	10:40 AM	Rick Dudley, Asst City Manager	Repair work taking place on pipe	Quick action to contain spill
V-15	4/3/07	10:40 AM	Rick Dudley, Asst City Manager	Repair work taking place on pipe	Quick action to contain spill
V-16	4/3/07	10:40 AM	Rick Dudley, Asst City Manager	Repair work taking place on pipe	Quick action to contain spill
V-17	4/3/07	10:40 AM	Rick Dudley, Asst City Manager	Repair work taking place on pipe	Quick action to contain spill
V-18	4/3/07	10:40 AM	Rick Dudley, Asst City Manager	Repair work taking place on pipe	Quick action to contain spill
V-19	4/3/07	10:40 AM	Rick Dudley, Asst City Manager	Repair work taking place on pipe	Quick action to contain spill
V-20	4/3/07	10:40 AM	Rick Dudley, Asst City Manager	Repair work taking place on pipe	Quick action to contain spill
V-21	4/3/07	10:40 AM	Rick Dudley, Asst City Manager	Repair work taking place on pipe	Quick action to contain spill
V-22	4/3/07	10:40 AM	Rick Dudley, Asst City Manager	Repair work taking place on pipe	Quick action to contain spill
V-23	4/3/07	10:40 AM	Rick Dudley, Asst City Manager	Repair work taking place on pipe	Quick action to contain spill
V-24	4/3/07	10:40 AM	Rick Dudley, Asst City Manager	Repair work taking place on pipe	Quick action to contain spill
V-25	4/3/07	10:40 AM	Rick Dudley, Asst City Manager	Repair work taking place on pipe	Quick action to contain spill
V-26	4/3/07	10:45 AM	Rick Dudley, Asst City Manager	Old pylon in excavation site	Quick action to contain spill
V-27	4/3/07	10:50 AM	Rick Dudley, Asst City Manager	Aerator installation	Quick action to contain spill
V-28	4/3/07	10:50 AM	Rick Dudley, Asst City Manager	Aerator in action	Quick action to contain spill
V-29	4/3/07	10:50 AM	Rick Dudley, Asst City Manager	Aerator in action	Quick action to contain spill
V-30	4/3/07	10:50 AM	Rick Dudley, Asst City Manager	Aerator in action	Quick action to contain spill
V-31	4/3/07	10:50 AM	Rick Dudley, Asst City Manager	Aerator in action	Quick action to contain spill
V-32	4/3/07	10:50 AM	Rick Dudley, Asst City Manager	Aerator in action	Quick action to contain spill
V-33	4/3/07	10:55 AM	Rick Dudley, Asst City Manager	Environmental surveying taking place	Quick action to contain spill
V-34	4/3/07	10:55 AM	Rick Dudley, Asst City Manager	Environmental surveying taking place	Quick action to contain spill
V-35	4/3/07	11:00 AM	Rick Dudley, Asst City Manager	Buena Vista lagoon	Quick action to contain spill
V-36	4/3/07	11:00 AM	Rick Dudley, Asst City Manager	Buena Vista lagoon	Quick action to contain spill
V-37	4/3/07	11:00 AM	Rick Dudley, Asst City Manager	Buena Vista lagoon	Quick action to contain spill
V-38	4/3/07	11:00 AM	Rick Dudley, Asst City Manager	Environmental surveying continues	Quick action to contain spill

V-2



V-4



V-1



V-3



V-6



V-8



V-5




V-7



V-10




V-12



V-9




V-11




V-14



V-16



V-13




V-15



V-18




V-20



V-17




V-19






ee-n



ee-n




ee-n



ee-n

V-24




SE-N



SE-N



SE-N



V-29



V-30



V-31



V-32



V-34




V-36




V-33



V-35



V-38



V-37



Buena Vista Spill Photos Encina Wastewater

PHOTO #	DATE	TIME	PHOTOGRAPHER	PHOTO SUMMARY	PHOTO RELEVANCE
EW-1	4/2/07	9:30 AM	John Fetu, EWA	BV Pump Station Wetwell Flood Electrical Conduit	Documentation of spill site
EW-2	4/2/07	9:30 AM	John Fetu, EWA	Flooded BV Pump Station Wet Well	Documentation of spill site
EW-3	4/2/07	9:30 AM	John Fetu, EWA	Vactor Truck Diversion Pumping BVPS	Quick Response to spill event
EW-4	4/2/07	9:32 AM	John Fetu, EWA	Atlas Pumping Flooded BVPS Containment area.	Quick Response to spill event
EW-5	4/2/07	9:46 AM	John Fetu, EWA	Verification of Time	Document spill event
EW-6	4/2/07	9:57 AM	John Fetu, EWA	Motor Room Floor, BVPS, Seal Water Reservoir	Document spill event
EW-7	4/2/07	9:57 AM	John Fetu, EWA	Motor Room Floor, BVPS, Seal Water and Conduits	Document spill event
EW-8	4/2/07	10:00 AM	John Fetu, EWA	Flooded Motor Room Floor, BVPS	Document spill event
EW-9	4/2/07	9:58 AM	John Fetu, EWA	BVPS Dry Well, Pump Discharge Force Main	Document spill event
EW-10	4/2/07	10:00 AM	John Fetu, EWA	BVPS Dry Well, Pipe Penetration Leakage	Document spill event
EW-11	4/2/07	10:00 AM	John Fetu, EWA	BVPS Dry Well Force Main	Document spill event
EW-12	4/2/07	10:05 AM	John Fetu, EWA	BVPS Ceiling in Dry Well With leaking Conduit Penetrations	Document spill event
EW-13	4/2/07	10:00 AM	John Fetu, EWA	BVPS Storm Door Seal Leaking	Document spill event
EW-14	4/2/07	10:05 AM	John Fetu, EWA	BVPS Sand Bags at Storm Door (leaking)	Document spill event
EW-15	4/2/07	10:26 AM	John Fetu, EWA	BVPS Wet Well Flooded	Document spill event
EW-16	4/2/07	10:26 AM	John Fetu, EWA	Float & Instrumentation at BVPS Wet Well (Flooded!)	Document spill event
EW-17	4/2/07	9:30 AM	John Fetu, EWA	BVPS Float & Instrumentation at Wet Well	Document spill event
EW-18	4/2/07	11:25 AM	John Fetu, EWA	VPS Flooded Wet Well (Top of Stairs with Handrail)	Document spill event
EW-19	4/3/07	3:00 PM	John Fetu, EWA	Removed Pipe Section	Document spill event
EW-20	4/3/07	3:00 PM	John Fetu, EWA	Removed Damaged Pipe	Document spill event
EW-21	4/3/07	3:00 PM	John Fetu, EWA	Damaged Pipe	Document spill event
EW-22	4/3/07	3:00 PM	John Fetu, EWA	Damaged Pipe	Document spill event
EW-23	4/3/07	3:00 PM	John Fetu, EWA	Damaged Pipe	Document spill event
EW-24	4/3/07	3:00 PM	John Fetu, EWA	Repaired Force Main	Documentation of repair
EW-25	4/3/07	12:00 PM	John Fetu, EWA	Contractor Working at Repair Site	Documentation of repair
EW-26	4/3/07	12:00 PM	John Fetu, EWA	BVPS Force Main at Jefferson St. Bridge	Document spill event
EW-27	4/3/07	12:00 PM	John Fetu, EWA	Excavating Force Main at Jefferson St. Bridge	Documentation of repair
EW-28	4/3/07	12:00 PM	John Fetu, EWA	Contractor at Repair Site, Shoring	Documentation of repair
EW-29	4/3/07	12:00 PM	John Fetu, EWA	Contractor Repairing Damaged Pipe	Documentation of repair
EW-30	4/3/07	12:00 PM	John Fetu, EWA	Contractor on site making Force Main repairs	Documentation of repair
EW-31	4/3/07	9:45 AM	Bruce Dale, Asst Operations Superintendent	South Gate, BVPS Containment Basin	Document spill event
EW-32	4/3/07	9:45 AM	Bruce Dale, Asst Operations Superintendent	Roof Top View, South Gate BVPS Containment Basin	Document spill event
EW-33	4/3/07	10:00 AM	Bruce Dale, Asst Operations Superintendent	South East Fenceline, BVPS, Creek Levee	Document spill event
EW-34	4/3/07	10:00 AM	Bruce Dale, Asst Operations Superintendent	Roof Top East View, BVPS Containment, Pump Back OPS	Quick Response to spill event
EW-35	4/3/07	10:00 AM	Bruce Dale, Asst Operations Superintendent	BVPS Influent Manhole Raw Sewage Upwelling at Containment Basin	Document spill event

Buena Vista Spill Photos Encina Wastewater

PHOTO #	DATE	TIME	PHOTOGRAPHER	PHOTO SUMMARY	PHOTO RELEVANCE
EW-36	4/3/07	10:00 AM	Bruce Dale, Asst Operations Superintendent	East Fenceline, BVPS, Atlas Pump Back Ops	Document spill event
EW-37	4/3/07	10:00 AM	Bruce Dale, Asst Operations Superintendent	Southeast View, BVPS Containment Basin, Containment level approaching levee breach	Document spill event
EW-38	4/3/07	10:00 AM	Bruce Dale, Asst Operations Superintendent	South View BVPS Containment Basin (blurred)	Document spill event
EW-39	4/3/07	10:00 AM	Bruce Dale, Asst Operations Superintendent	Pump back operation lined up on Jefferson St.	Quick Response to spill event
EW-40	4/3/07	10:00 AM	Bruce Dale, Asst Operations Superintendent	BVPS "Surge Tank", West View, Flooded	Document spill event
EW-41	4/3/07	10:00 AM	Bruce Dale, Asst Operations Superintendent	BVP Potable Water Air Gap Tank in Flooded Containment Basin	Document spill event
EW-42	4/3/07	10:00 AM	Bruce Dale, Asst Operations Superintendent	West View, East Side BVPS, Storm Drain With Atlas Pump Back Ops	Quick Response to spill event
EW-43	4/3/07	10:00 AM	Bruce Dale, Asst Operations Superintendent	East Side BVPS Pump Back Ops at Storm Drain Overflow.	Quick Response to spill event
EW-44	4/3/07	10:00 AM	Bruce Dale, Asst Operations Superintendent	West View BVPS Containment Basin, Flooded	Document spill event
EW-45	4/3/07	10:00 AM	Bruce Dale, Asst Operations Superintendent	East View, Flooded, BVPS Containment Basin	Document spill event
EW-46	4/3/07	10:00 AM	Bruce Dale, Asst Operations Superintendent	North View Flooded BVPS Containment Basin	Document spill event
EW-47	4/3/07	10:00 AM	Bruce Dale, Asst Operations Superintendent	South View Levee Breach Area BVPS	Document spill event
EW-48	4/3/07	10:10 AM	Bruce Dale, Asst Operations Superintendent	Levee Breach Area, BVPS	Document spill event
EW-49	4/3/07	10:15 AM	Bruce Dale, Asst Operations Superintendent	Sewage Overflow into Storm drain at BVPS	Document spill event
EW-50	4/3/07	10:15 AM	Bruce Dale, Asst Operations Superintendent	Air Reservoir at BVPS - Flooded	Document spill event
EW-51	4/3/07	10:20 AM	Bruce Dale, Asst Operations Superintendent	South View BVPS Storm Door, Flooding & Spilling over the Levee.	Document spill event
EW-52	4/3/07	10:20 AM	Bruce Dale, Asst Operations Superintendent	Southeast View BVPS storm door, Flooded & Spilling	Document spill event
EW-53	4/3/07	10:20 AM	Bruce Dale, Asst Operations Superintendent	Southwest View BVPS, Flooded & Spilling	Document spill event
EW-54	4/3/07	10:20 AM	Bruce Dale, Asst Operations Superintendent	West View Flooded BVPS containment basin	Document spill event
EW-55	4/3/07	10:20 AM	Bruce Dale, Asst Operations Superintendent	South West View Flooded BVPS Containment & Levee	Document spill event

**Buena Vista Spill Photos
Encina Wastewater**

PHOTO #	DATE	TIME	PHOTOGRAPHER	PHOTO SUMMARY	PHOTO RELEVANCE
EW-56	4/3/07	10:20 AM	Bruce Dale, Asst Operations Superintendent	South View BVPS Containment Basin	Document spill event
EW-57	4/3/07	10:20 AM	Bruce Dale, Asst Operations Superintendent	South View, Flooded BVPS Containment Basin	Document spill event
EW-58	4/3/07	10:30 AM	Bruce Dale, Asst Operations Superintendent	Southeast View, Flooded BVPS Storm Door.	Document spill event
EW-59	4/3/07	10:30 AM	Bruce Dale, Asst Operations Superintendent	East View Flooded BVPS Storm Door	Document spill event
EW-60	4/3/07	10:50 AM	Bruce Dale, Asst Operations Superintendent	BVPS South Gate, Flooded	Document spill event
EW-61	4/4/07	7:00 AM	Bruce Dale, Asst Operations Superintendent	BVPS Lagoon/Channel Pump Back Mitigation Effort two pumps and hoses run to BVPS influent wet well	Quick Response to spill event
EW-62	4/4/07	7:00 AM	Bruce Dale, Asst Operations Superintendent	BVPS Lagoon / Channel Pump back mitigation effort 2 pump discharge lines to BVPS influent wet well manhole. East View fence line with rags and debris.	Quick Response to spill event
EW-63	4/4/07	7:15 AM	Bruce Dale, Asst Operations Superintendent	BVPS, Roof Top view of fence line with rags	Document spill event
EW-64	4/4/07	7:30 AM	Bruce Dale, Asst Operations Superintendent	BVPS, Southwest view, containment basin drain clean-up	Quick Response to spill event

EW-2




EW-1



EW4



EW-3





EW-4



EW-8



EW-6



EW-7

EW-10




EW-12



EW-9



EW-11



Ew-14



Ew-14



Ew-13



Ew-15





Ew-18



Ew-17



Ew-20




Ew-19

EW-22



EW-24



EW-21



EW-23



EW-24



EW-28




EW-25




EW-27



Ew 30



Ew-29



Ew-32



Ew-31




EW-34



EW-36



EW-33



EW-35



EW-38



EW-46




EW-37




EW-39



EW-41



EW-42




EW 43




EW 44



Ew-45



Ew-46



Ew 47



Ew 48




EW50



EW - 52



EW49




EW51



Ew-54



Ew-54



Ew-53




Ew-55




EW-57



EW-58



EW-59



EW-60



EW-602



EW-604



EW-601



EW-603



Summary of Buena Vista Lagoon Annotated Photographs Taken by Weston Solutions

Due to the high volume of pictures that were captured by Weston Solutions personnel, only a fraction of the total pictures were annotated and placed into Microsoft word documents. All pictures, however, both annotated and non-annotated, are provided on a CD ROM from each day that Weston Solutions performed monitoring. For each annotated picture, the picture ID consists of the numeric date followed by a dashed line and the picture number. For example, the 5th picture annotated on April 3, 2007 would have the photo ID of "43-5". Sediment samples taken on April 4 and 5 are indicated by an S after the date in the photo ID. Within each annotation, the photo ID is followed by the date, time, photographer, photo description, and direction the camera was pointed when the picture was taken. In some instances, the view, or camera direction was not provided if the camera was directed downward at the water or if the camera angle could not be determined due to a lack of landmarks.



W43-1: Date: April 3, 2007 Time: 10:59am. Photographer: N. Woodward
Description: Crane and backhoe performing maintenance on broken pipe
View: Southeast



W43-2: Date: April 3, 2007 Time: 11:00am. Photographer: E. Goldstein
Description: Various species of dead fish collected from East Basin



W43-3: **Date:** April 3, 2007 **Time:** 11:05am. **Photographer:** N. Woodward
Description: Aeration pump used to increase DO in East Basin
View: Northeast



W43-4: **Date:** April 3, 2007 **Time:** 11:26am. **Photographer:** N. Woodward
Description: East Basin waterline **View:** South



W43-5: **Date:** April 3, 2007 **Time:** 11:32am. **Photographer:** N. Woodward
Description: East Basin waterline **View:** North



W43-6: **Date:** April 3, 2007 **Time:** 11:54am. **Photographer:** E. Goldstein
Description: Aeration pump used to increase DO in East Basin
View: Northeast



W43-7: Date: April 3, 2007 **Time:** 11:54am. **Photographer:** N. Woodward
Description: Foam on water surface of East Basin **View:** East



W43-8: Date: April 3, 2007 **Time:** 11:54am. **Photographer:** N. Woodward
Description: Jefferson Street Bridge **View:** East



W43-9: **Date:** April 3, 2007 **Time:** 11:54am. **Photographer:** N. Woodward
Description: Media around East Basin **View:** East northeast



W43-10: **Date:** April 3, 2007 **Time:** 12:06pm. **Photographer:** N. Woodward
Description: Aeration pump used to increase DO in East Basin
View: Northeast



W43-11: Date: April 3, 2007 **Time:** 12:07pm. **Photographer:** N. Woodward
Description: Catfish at the surface in East Basin



W43-12: Date: April 3, 2007 **Time:** 12:14pm. **Photographer:** N. Woodward
Description: Dead green sunfish collected in East Basin



W43-13: **Date:** April 3, 2007 **Time:** 12:22pm. **Photographer:** N. Woodward
Description: Algae clumps on water surface in East Basin
View: North



W43-14: **Date:** April 3, 2007 **Time:** 12:22pm. **Photographer:** N. Woodward
Description: Crane and backhoe performing maintenance on broken pipe
View: Southeast



W43-15: Date: April 3, 2007 Time: 12:56pm. Photographer: N. Woodward
Description: Water surface in East Basin showing algal mats **View:** Northeast



W43-16: Date: April 3, 2007 Time: 12:56pm. Photographer: N. Woodward
Description: East Basin waterline **View:** West



W43-17: Date: April 3, 2007 Time: 12:56pm. Photographer: N. Woodward
Description: Dislodged benthic algal clumps in East Basin View: Southeast



W43-18: Date: April 3, 2007 Time: 12:57pm. Photographer: N. Woodward
Description: Dislodged benthic algal clumps on water surface in East Basin



W43-19: Date: April 3, 2007 **Time:** 13:26pm. **Photographer:** N. Woodward
Description: Reeds in East Basin **View:** West



W43-20: Date: April 3, 2007 **Time:** 14:55pm. **Photographer:** N. Woodward
Description: Water siphon from aeration pump in East Basin **View:** South



W43-21: Date: April 3, 2007 **Time:** 15:32pm. **Photographer:** N. Woodward
Description: Water and reeds near Coast Hwy Middle Basin **View:** Northwest



W43-22: Date: April 3, 2007 **Time:** 16:08pm. **Photographer:** N. Woodward
Description: Reeds and water in Middle Basin **View:** Southeast



W43-23: Date: April 3, 2007 Time: 16:33pm. Photographer: N. Woodward
Description: Foam on water-Middle Basin View: South



W43-24: Date: April 3, 2007 Time: 16:34pm. Photographer: N. Woodward
Description: Reeds and water in Middle Basin View: Northeast



W43-25: **Date:** April 3, 2007 **Time:** 16:48pm. **Photographer:** N. Woodward
Description: Reeds and water in Middle Basin **View:** undetermined



W43-26: **Date:** April 3, 2007 **Time:** 16:57pm. **Photographer:** N. Woodward
Description: Reeds and water in Middle Basin **View:** North



W43-27: Date: April 3, 2007 Time: 16:58pm. Photographer: N. Woodward
Description: Reeds and water in Middle Basin View: South



W43-28: Date: April 3, 2007 Time: 17:09pm. Photographer: N. Woodward
Description: Reeds in Middle Basin View: West



W43-29: Date: April 3, 2007 Time: 17:32pm. Photographer: E. Goldstein
Description: Inflatable boat used for lagoon monitoring, Middle Basin
View: East



W43-30: Date: April 3, 2007 Time: 17:33pm. Photographer: N. Woodward
Description: Bagged dead fish collected from East Basin



W43-31: Date: April 3, 2007 **Time:** 17:33pm. **Photographer:** N. Woodward
Description: Dead fish collected from East Basin



W44-1 Date: April 4, 2007 **Time:** 7:21am. **Photographer:** A. Glassco
Description: Foam on water, East Basin @ Jefferson Bridge **View:** Southeast



W44-2 Date: April 4, 2007 **Time:** 7:21am. **Photographer:** A. Glassco
Description: Foam on water, East Basin near Jefferson Bridge **View:** North



W44-3 Date: April 4, 2007 Time: 7:21am. Photographer: A. Glassco
Description: Foam on water, East Basin near Jefferson Bridge View: West



W44-4 Date: April 4, 2007 Time: 7:35am. Photographer: A. Glassco
Description: Dead fish near reeds in East Basin View: North



W44-5 Date: April 4, 2007 Time: 7:36am. Photographer: A. Glassco
Description: East Basin water View: South



W44-6 Date: April 4, 2007 Time: 7:36am. Photographer: A. Glassco
Description: East Basin channel View: West



W44-7 Date: April 4, 2007 Time: 8:10am. Photographer: A. Glassco
Description: East Basin reeds and water View: South



W44-8 Date: April 4, 2007 Time: 8:10am. Photographer: A. Glassco
Description: East Basin water and reeds View: North



W44-9 Date: April 4, 2007 **Time:** 8:18am. **Photographer:** A. Glassco
Description: East Basin water and reeds **View:** South



W44-10 Date: April 4, 2007 **Time:** 8:18am. **Photographer:** A. Glassco
Description: East Basin water and reeds **View:** North



W44-11 Date: April 4, 2007 **Time:** 8:32am. **Photographer:** A. Glassco
Description: D. Owen (Weston Solutions, Inc.) conducting water quality monitoring in East Basin **View:** North



W44-12 Date: April 4, 2007 **Time:** 8:32am. **Photographer:** A. Glassco
Description: Water and reeds in Middle East Basin **View:** East



W44-13 Date: April 4, 2007 Time: 8:32am. Photographer: A. Glassco
Description: Water and reeds in west East Basin View: Northeast



W44-14 Date: April 4, 2007 Time: 8:32am. Photographer: A. Glassco
Description: Water and reeds in west East Basin View: Southeast



W44-15 Date: April 4, 2007 **Time:** 8:40am. **Photographer:** A. Glassco
Description: Cloudy water in west East Basin **View:** Undetermined



W44-16 Date: April 4, 2007 **Time:** 9:30am. **Photographer:** A. Glassco
Description: Aeration pump near Jefferson Street in East Basin **View:** Northeast



W44-17 Date: April 4, 2007 Time: 9:30am. Photographer: A. Glassco
Description: East Basin waters View: North



W44-18 Date: April 4, 2007 Time: 9:30am. Photographer: A. Glassco
Description: East Basin waters near Jefferson View: East



W44-19 Date: April 4, 2007 **Time:** 10:32am. **Photographer:** A. Glassco
Description: Dead fish collection in East Basin **View:** North



W44-20 Date: April 4, 2007 **Time:** 10:33am. **Photographer:** A. Glassco
Description: Foam on water in East Basin **View:** North



W44-21 Date: April 4, 2007 Time: 10:33am. Photographer: A. Glassco
Description: Close-up view of foam on water in East Basin



W44-22 Date: April 4, 2007 Time: 12:40pm. Photographer: A. Glassco
Description: Close-up view of benthic algal mats in East Basin



W44-23 Date: April 4, 2007 Time: 14:09pm. Photographer: A. Glassco
Description: East Basin water View: South



W44-24 Date: April 4, 2007 Time: 14:24pm. Photographer: A. Glassco
Description: East Basin aeration near Jefferson View: Southeast



W44-25 Date: April 4, 2007 Time: 14:43pm. Photographer: A. Glassco
Description: Algal mats on East Basin surface water View: South



W44-26 Date: April 4, 2007 Time: 14:49pm. Photographer: A. Glassco
Description: Algal mats on East Basin surface water View: South



W44-27 Date: April 4, 2007 Time: 14:57pm. Photographer: A. Glassco
Description: East Basin channel View: Northeast



W44-28 Date: April 4, 2007 Time: 15:22pm. Photographer: A. Glassco
Description: East Basin channel View: South



W44-29 Date: April 4, 2007 Time: 15:42pm. Photographer: A. Glassco
Description: West end of East Basin View: East



W44-30 Date: April 4, 2007 Time: 7:05am. Photographer: N. Woodward
Description: Middle Basin Bridge at Coast Hwy View: West



W44-31 Date: April 4, 2007 Time: 7:05am. Photographer: N. Woodward
Description: Middle Basin near Bridge at Coast Hwy View: North



W44-32 Date: April 4, 2007 Time: 7:35am. Photographer: N. Woodward
Description: Middle Basin waters View: South



W44-33 Date: April 4, 2007 Time: 8:22am. Photographer: N. Woodward
Description: Middle Basin waters View: Northwest



W44-34 Date: April 4, 2007 Time: 8:45am. Photographer: N. Woodward
Description: Middle Basin waters View: Northeast



W44-35 Date: April 4, 2007 Time: 8:52am. Photographer: N. Woodward
Description: Middle Basin reeds and water View: South



W44-36 Date: April 4, 2007 Time: 13:28pm. Photographer: N. Woodward
Description: Middle Basin reeds and water near Coast Hwy Bridge
View: Northwest



W44-37 Date: April 4, 2007 Time: 14:18pm. Photographer: N. Woodward
Description: Middle Basin reeds and water View: South



W44-38 Date: April 4, 2007 Time: 14:56pm. Photographer: N. Woodward
Description: Middle Basin reeds and water View: South



W44S-1 Date: April 4, 2007 **Time:** 15:55pm. **Photographer:** D. McCoy
Description: Deployment of Eckman grab sampler for benthic sampling, East Basin



W44S-2 Date: April 4, 2007 **Time:** 15:55pm. **Photographer:** D. McCoy
Description: Sediment sample from Eckman grab sampler, East Basin



W44S-3 Date: April 4, 2007 Time: 15:55pm. Photographer: D. McCoy
Description: East Basin water View: North



W44S-4 Date: April 4, 2007 Time: 15:55pm. Photographer: D. McCoy
Description: Aeration pump in East Basin View: North



W44S-5 Date: April 4, 2007 **Time:** 17:32pm. **Photographer:** D. McCoy
Description: Homogenated West Basin sediment from Eckman grab sampler



W45S-1 Date: April 5, 2007 **Time:** 11:16am. **Photographer:** B. Isham
Description: West Basin sediment in Eckman grab sampler



W45-1: Date: April 5, 2007 **Time:** 7:10am. **Photographer:** D. Owen
Description: East Basin aeration **View:** East



W45-2: Date: April 5, 2007 **Time:** 7:25am. **Photographer:** D. Owen
Description: Foam in East Basin at Jefferson Bridge **View:** East



W45-3: Date: April 5, 2007 **Time:** 7:25am. **Photographer:** D. Owen
Description: Foam in East Basin south of Jefferson Bridge **View:** South



W45-4: Date: April 5, 2007 **Time:** 7:25am. **Photographer:** D. Owen
Description: Aeration foam in East Basin **View:** Southwest



W45-5: Date: April 5, 2007 **Time:** 7:42am. **Photographer:** D. Owen
Description: Muskovy duck in East Basin **View:** Southwest



W45-6: Date: April 5, 2007 **Time:** 7:51am. **Photographer:** D. Owen
Description: Surface water in East Basin **View:** Northwest



W45-7: **Date:** April 5, 2007 **Time:** 7:51am. **Photographer:** D. Owen
Description: Surface water in East Basin **View:** Southwest



W45-8: **Date:** April 5, 2007 **Time:** 8:11am. **Photographer:** D. Owen
Description: Surface water and reeds in East Basin **View:** West



W45-9: Date: April 5, 2007 Time: 8:11am. Photographer: D. Owen
Description: Algal mats in East Basin along reeds



W45-10: Date: April 5, 2007 Time: 8:33am. Photographer: C. Hartman
Description: East Basin water and reeds View: South



W45-11: Date: April 5, 2007 **Time:** 9:16am. **Photographer:** C. Hartman
Description: East Basin water quality measurements using YSI **View:** East



W45-12: Date: April 5, 2007 **Time:** 13:48pm. **Photographer:** T. Wells
Description: East Basin foam at Jefferson Bridge **View:** East



W45-13: Date: April 5, 2007 Time: 13:48pm. Photographer: T. Wells
Description: East Basin foam south of Jefferson Bridge View: Northeast



W45-14: Date: April 5, 2007 Time: 13:48pm. Photographer: T. Wells
Description: Recording field observations East Basin View: West



W45-15: Date: April 5, 2007 Time: 14:13pm. Photographer: T. Wells
Description: East Basin algal mats View: Northwest



W45-16: Date: April 5, 2007 Time: 14:28pm. Photographer: T. Wells
Description: Great Blue Heron- East Basin View: West



W45-17: Date: April 5, 2007 **Time:** 14:28pm. **Photographer:** T. Wells
Description: West end of East Basin **View:** West



W45-18: Date: April 5, 2007 **Time:** 14:46pm. **Photographer:** N. Woodward
Description: Dead fish collected from East Basin



W45-19: Date: April 5, 2007 **Time:** 15:34pm. **Photographer:** T. Wells
Description: Wakes caused by fish in East Basin



W45-20: Date: April 5, 2007 **Time:** 6:55am. **Photographer:** N. Spear
Description: Middle Basin water **View:** Southeast



W45-21: Date: April 5, 2007 **Time:** 6:55am. **Photographer:** N. Spear
Description: Common tern in Middle Basin **View:** Southeast



W45-22: Date: April 5, 2007 **Time:** 7:54am. **Photographer:** N. Spear
Description: Middle Basin waterline **View:** Northeast



W45-23: Date: April 5, 2007 **Time:** 7:54am. **Photographer:** N. Spear
Description: Middle Basin water and reeds **View:** North



W45-24: Date: April 5, 2007 **Time:** 9:28am. **Photographer:** N. Woodward
Description: Westernmost portion of Middle Basin **View:** West



W45-25: Date: April 5, 2007 **Time:** 9:28am. **Photographer:** N. Woodward
Description: Coast highway bridge at west end of Middle Basin **View:** West



W45-26: Date: April 5, 2007 **Time:** 14:02pm. **Photographer:** N. Woodward
Description: Great Blue Heron- Middle Basin **View:** Northeast



W46-1 Date: April 6, 2007 **Time:** 6:47am. **Photographer:** C. Hartman
Description: Aeration at Jefferson Bridge, East Basin **View:** Northeast



W46-2 Date: April 6 2007 **Time:** 6:54am. **Photographer:** C. Hartman
Description: Foam in East Basin **View:** Southeast



W46-3 Date: April 6, 2007 Time: 7:12am. Photographer: C. Hartman
Description: East Basin aeration View: Southwest



W46-4 Date: April 6, 2007 Time: 9:02am. Photographer: C. Hartman
Description: Dead fish in East Basin along reeds View: Undetermined



W46-5 Date: April 6, 2007 Time: 9:50am. Photographer: C. Hartman
Description: Surface water and foam in East Basin View: Southeast



W46-6 Date: April 6, 2007 Time: 9:50am. Photographer: C. Hartman
Description: East Basin surface water, foam, and tractor View: Southeast



W46-7 Date: April 6, 2007 Time: 9:50am. Photographer: C. Hartman
Description: East Basin aerator west of Jefferson Bridge View: East



W46-8 Date: April 6, 2007 Time: 9:50am. Photographer: C. Hartman
Description: East Basin aerator and foam View: Northeast



W46-9 Date: April 6, 2007 Time: 10:19am. Photographer: C. Hartman
Description: Foam and dead fish east of Jefferson Bridge, East Basin
View: East



W46-10 Date: April 6, 2007 Time: 10:21am. Photographer: C. Hartman
Description: East Basin foam, dead fish, and algae east of Jefferson Bridge




W46-11 Date: April 6, 2007 Time: 10:22am. Photographer: C. Hartman
Description: Foam east of Jefferson Bridge, East Basin View: West



W46-12 Date: April 6, 2007 Time: 10:22am. Photographer: C. Hartman
Description: Aerator in East Basin upstream from Jefferson Bridge
View: North



W46-13 Date: April 6, 2007 Time: 11:05am. Photographer: C. Hartman
Description: East Basin aerator View: North



W46-14 Date: April 6, 2007 Time: 7:03am. Photographer: A. Glassco
Description: Moscovy duck eating in Middle Basin



W46-15 Date: April 6, 2007 **Time:** 7:48am. **Photographer:** N. Spears
Description: Surface water and reeds in Middle Basin



W46-16 Date: April 6, 2007 **Time:** 8:11am. **Photographer:** A. Glassco
Description: Surface water in Middle Basin **View:** South



W46-17 Date: April 6, 2007 **Time:** 10:53am. **Photographer:** N. Spears
Description: Dead California gull in the Middle Basin



W46-18 Date: April 6, 2007 **Time:** 11:12am. **Photographer:** A. Glasco
Description: Bird egg in the Middle Basin



W47-1: Date: April 7, 2007 **Time:** 6:56am. **Photographer:** D. Owen
Description: Aeration foam, data recording East Basin **View:** East



W47-2: Date: April 7, 2007 **Time:** 7:35am. **Photographer:** D. Owen
Description: Aeration hose, foam, algae along south shore of East Basin **View:** South



W47-3: Date: April 7, 2007 Time: 8:30am. Photographer: D. Owen
Description: Great egrets standing in East Basin View: North



W47-4: Date: April 7, 2007 Time: 17:27pm. Photographer: T. Wells
Description: Counting, measuring, and identifying dead fish at Weston Solutions



W47-5: Date: April 7, 2007 Time: 17:27pm. Photographer: T. Wells
Description: Counting, measuring, and identifying dead fish at Weston Solutions



W47-6: Date: April 7, 2007 Time: 17:27pm. Photographer: T. Wells
Description: Sorted dead goldfish



W47-7: Date: April 7, 2007 Time: 17:27pm. Photographer: T. Wells
Description: Dead bird taxonomy and processing



W47-8: Date: April 7, 2007 Time: 17:28pm. Photographer: T. Wells
Description: Measuring and classifying dead fish



W47-9: Date: April 7, 2007 Time: 17:28pm. Photographer: T. Wells
Description: Measuring and classifying dead gadwall



W47-10: Date: April 7, 2007 Time: 17:30pm. Photographer: T. Wells
Description: Processing of coolers containing dead fish and birds at Weston Solutions



W47-11: Date: April 7, 2007 **Time:** 7:55am. **Photographer:** C. Hartman
Description: Dead coot, Middle Basin



W47-12: Date: April 7, 2007 **Time:** 8:04am. **Photographer:** C. Hartman
Description: Middle Basin backwater and reeds **View:** East