NOTICE OF VIOLATION No. R9-2017-0108

Mrs. Sue Vinck 2256 Durasno Lane Spring Valley, California 91977 Violation of 13267 Directive

July 7, 2017

Mrs. Sue Vinck is hereby notified that the California Regional Water Quality Control Board, San Diego Region (San Diego Water Board), reserves the right to take any enforcement action authorized by law for the violation described herein.

You are in violation of a directive issued to you by the San Diego Water Board under authority of Water Code section 13267. The directive was issued in a letter dated June 6, 2017, with the subject *Water Code Section 13267 Directive for Technical Reports – Palomar Cleaners, 7870 Broadway, Lemon Grove, California.*

A. Summary of Violation

Failure to Furnish Indoor Air Sampling Work Plan

Directive A of the June 6 letter requires you to furnish an Indoor Air Sampling Work Plan (Work Plan) that describes collection and analysis of indoor air samples to evaluate the potential risk to human health from vapor intrusion into buildings overlying the groundwater plume emanating from Palomar Cleaners. Directive A required the Work Plan be received by the San Diego Water Board no later than 5:00 p.m. on June 20, 2017. The Work Plan has not been received.

B. Summary of Potential Enforcement Options

The violation cited above may subject you to additional enforcement by the San Diego Water Board, including a potential civil liability assessment of \$1,000 for each day in which the violation occurs pursuant to Water Code section 13268. Be advised that you have been and will be in violation of the section 13267 directive every day from June 20, 2017, until an adequate Indoor Air Sampling Work Plan is received by the San Diego Water Board. The Board may also take any of the following administrative or enforcement actions:

Other Potential Enforcement Options	Applicable Water Code Section
Technical or Investigative Order	Section 13267
Cleanup and Abatement Order	Section 13304
Cease and Desist Order	Sections 13301-13303
Time Schedule Order	Sections 13300, 13308

Julie Chan, PG

_____ Chief, Site Restoration and Groundwater Protection Branch

JC/jpa/sam

Tech Staff Info & Use	
Geotracker Global ID	T0608121884
Cost Recovery ID	N/A