| Report date: | |
|-------------------|--|
| Case Description: | |

5/26/2021 Demolition

| Description | Affected Land Use |
|----------------------------|-------------------|
| Demolition 82 Feet Distant | Residential |

| | | I | Equipment | : | |
|------------------------|--------|----------|-----------|--------|----------|
| | | | Spec | Actual | Receptor |
| | Impact | | Lmax | Lmax | Distance |
| Description | Device | Usage(%) | (dBA) | (dBA) | (feet) |
| Other Equipment | No | 50 | 85 | | 82 |
| Skid Steer Loader | No | 40 | | 79.1 | 82 |
| Tractor/Loader/Backhoe | No | 40 | 84 | | 82 |

Calculated (dBA)

| Equipment | *Lmax | Leq |
|------------------------|-------|------|
| Other Equipment | 80.7 | 77.7 |
| Skid Steer Loader | 74.8 | 70.8 |
| Tractor/Loader/Backhoe | 79.7 | 75.7 |
| Total | 80.7 | 80.3 |

Report date: Case Description: 5/26/2021 Site Preparation

| Description | Affected Land Use |
|----------------------------------|-------------------|
| Site Preparation 82 Feet Distant | Residential |

| | | E | Equipment | : | |
|------------------------|--------|----------|-----------|--------|----------|
| | | | Spec | Actual | Receptor |
| | Impact | | Lmax | Lmax | Distance |
| Description | Device | Usage(%) | (dBA) | (dBA) | (feet) |
| Other Equipment | No | 50 | 85 | | 82 |
| Skid Steer Loader | No | 40 | | 79.1 | 82 |
| Tractor/Loader/Backhoe | No | 40 | 84 | | 82 |

Calculated (dBA)

| Equipment | *Lmax | Leq |
|------------------------|-------|------|
| Other Equipment | 80.7 | 77.7 |
| Skid Steer Loader | 74.8 | 70.8 |
| Tractor/Loader/Backhoe | 79.7 | 75.7 |
| Total | 80.7 | 80.3 |

| Report date: | 5/26 |
|-------------------|------|
| Case Description: | G |

26/2021 Grading

| Description | Affected Land Use |
|-------------------------|-------------------|
| Grading 82 Feet Distant | Residential |

| | | | Equipment | | |
|------------------------|--------|----------|-----------|--------|----------|
| | | | Spec | Actual | Receptor |
| | Impact | | Lmax | Lmax | Distance |
| Description | Device | Usage(%) | (dBA) | (dBA) | (feet) |
| Excavator | No | 40 | | 80.7 | 82 |
| Other Equipment | No | 50 | 85 | | 82 |
| Tractor/Loader/Backhoe | No | 40 | 84 | | 82 |

Calculated (dBA)

| Equipment | *Lmax | Leq |
|------------------------|-------|------|
| Excavator | 76.4 | 72.4 |
| Other Equipment | 80.7 | 77.7 |
| Tractor/Loader/Backhoe | 79.7 | 75.7 |
| Total | 80.7 | 80.6 |

Report date: Case Description: 5/26/2021 Construction

| Description | Affected Land Use |
|------------------------------|-------------------|
| Construction 82 Feet Distant | Residential |

| | | E | Equipment | | |
|------------------------|------------------|----------|---------------|---------------|--------------------|
| | • • • • • • | | Spec | Actual | Receptor |
| Description | Impact Device | Usage(%) | Lmax (dBA) | Lmax (dBA) | Distance (feet) |
| Excavator | No | 40 | (0.2.1) | 80.7 | 82 |
| Other Equipment | No | 50 | 85 | | 82 |
| Skid Steer Loader | No | 40 | | 79.1 | 82 |
| Tractor/Loader/Backhoe | No | 40 | 84 | | 82 |

Calculated (dBA)

| Equipment | *Lmax | Leq |
|------------------------|-------|------|
| Excavator | 76.4 | 72.4 |
| Other Equipment | 80.7 | 77.7 |
| Skid Steer Loader | 74.8 | 70.8 |
| Tractor/Loader/Backhoe | 79.7 | 75.7 |
| Total | 80.7 | 81 |

| Report date: | 5, |
|-------------------|----|
| Case Description: | |

/26/2021 Paving

DescriptionAffected Land UsePaving 82 Feet DistantResidential

| | | E | Equipment | : | |
|------------------|--------|----------|--------------|----------------|----------------------|
| | Impact | | Spec Lmax | Actual Lmax | Receptor Distance |
| Description | Device | Usage(%) | (dBA) | (dBA) | (feet) |
| Other Equipment | No | 50 | 85 | | 82 |
| Paver | No | 50 | | 77.2 | 82 |
| Paving Equipment | No | 20 | | 89.5 | 82 |
| Roller | No | 20 | | 80 | 82 |

Calculated (dBA)

| Equipment | | *Lmax | Leq |
|------------------|-------|-------|------|
| Other Equipment | | 80.7 | 77.7 |
| Paver | | 72.9 | 69.9 |
| Paving Equipment | | 85.2 | 78.2 |
| Roller | | 75.7 | 68.7 |
| | Total | 85.2 | 81.5 |

| Report date: | 5/26/2021 |
|-------------------|-----------|
| Case Description: | Painting |

| Description | Affected Land Use |
|--------------------------|-------------------|
| Painting 82 Feet Distant | Residential |

Total

| | | | Equipment | | |
|-----------------|--------|----------|-----------|--------|----------|
| | | | Spec | Actual | Receptor |
| | Impact | | Lmax | Lmax | Distance |
| Description | Device | Usage(%) | (dBA) | (dBA) | (feet) |
| Other Equipment | No | 50 | 85 | | 82 |

Calculated (dBA)

| Equipment | |
|-----------------|--|
| Other Equipment | |

| *Lmax | Leq | |
|-------|------|--|
| 80.7 | 77.7 | |
| 80.7 | 77.7 | |