

Solstice Creek Fish Barrier Photograph Description

Photographer:

Kevin Jontz, Restoration and Monitoring Specialist- Heal the Bay Stream Team

Rationale:

Endangered Steelhead Trout face multiple barriers to upstream migration in Solstice Creek at Leo Carrillo State Park. These photos were taken to provide further evidence that fish barriers are present in Solstice Creek.

Photo Description:

Date, Time, Latitude and Longitude of photographs are imbedded in each image. Details of the camera and camera settings are in photo properties (right click image file, click properties, see tab titled "Details")



SOLSTIC E01-Looking upstream Solstice Creek directly at Barrier 4



SOLSTICE02-Looking upstream from an angle at Barrier 4



SOLSTICE03-Looking upstream Solstice Creek at Barrier 3



SOLSTICE04-Looking upstream Solstice Creek at Barrier 3

Spatial Representation:

