

# Tuna Canyon Creek Photograph Description

---

## *Photographer:*

Kevin Jontz, Restoration and Monitoring Specialist- Heal the Bay Stream Team

## *Rationale:*

These photos were taken to illustrate the trash impact to Tuna Canyon Creek.

## *Photo Description:*

Date, Time, Latitude and Longitude of photographs are imbedded in each image. Details of the camera and camera settings are in photo properties (right click image file, click properties, see tab titled "Details")



Photo #1 -Picture taken looking upstream





Photo #2 - The right bank of the creek looking downstream





Photo #3 - Looking Downstream





Photo #4 - Looking Downstream





Photo #5 - Picture taken looking downstream



