


Facility Inspection Report Photos – 8/31/01




1. Debris in Chollas Creek bed east of Harbor Drive



2. Debris in Chollas Creek bed east of Harbor Drive.



3. Trash directly upland from Chollas Creek east of Harbor Drive



4. Multiple spray paint cans in Chollas Creek east of Market St.



5. Spray paint cans and debris in Chollas Creek bed under Market St.



6. Trash in Chollas Creek bed east of Market St.



7. Various shredded pieces of trash snagged branch in Chollas Creek bed east of Market St.



8. Couch and other trash in Chollas Creek bed east of Market St.