



Facility Inspection Report Photos – 11/8/02

1. Trash on banks and instream at National Ave.



2. Trash on banks at National Ave.




3. Trash instream at National Ave.



4. Trash on banks at National Ave.



5. Trash at storm drain outlet at National Ave.



6. Trash lining length of bank at National Ave.



7. Trash instream at National Ave.



8. Trash on both banks and instream at National Ave.



9. Illegal dumping on bank at National Ave.



10. Illegal dumping on bank at National Ave.



11. New trash cans at NASSCO parking lot adjacent to mouth of Chollas Creek.



12. Trash in NASSCO parking lot adjacent to mouth of Chollas Creek.



13. New fence at NASSCO parking lot.




14. New fence intercepting trash before it can enter stream.



15. Trash on banks at mouth of Chollas Creek.



16. Trash on banks at mouth of Chollas Creek.



17. Trash on banks at mouth of Chollas Creek.




18. Trash instream at mouth of Chollas Creek.



19. Trash in creek at Market St.



20. Shopping cart in creek at Market St.



21. Trash on both banks at Main St..