



Facility Inspection Report Photos – 2/15/02

1. Significant amounts of trash on banks at mouth of Chollas Creek.



2. Trash in parking lot adjacent to mouth of Chollas Creek.



3. Small amounts of trash in Chollas Creek at Market Street.



4. Chollas Creek at Market Street.



5. Evidence of dumping into Paleta Creek by resident at 42nd St.



6. Near mouth of Paleta Creek.