



Figure 5C.4-27. Bench Habitat Analysis Sites

10-sediment insertion and bench test resulted in raising bed of waterway  
 6,7 Large trees down placed in waterway near banks to capture sediment & reduce waterway navigation and use in this area  
 3 bench built up and planted with tules but was infested with egeria densa which is not suitable for salmonids. Also causes flood control issues as bench reduces water outflow in high flow times.